

### SAFE HOME / LEADSAFE CHARLOTTE

### CITY OF CHARLOTTE

HOUSING & NEIGHBORHOOD SERVICES

### **BID OPENING CERTIFICATION RECORD**

Date of Bid Walk: 8	2/19		Due Date:	3/9/18	7	HNS _	19	<u>'- /</u>
			Public Body	· Estimate				
Address	РВ	E Ar	nount	PBE -15	5%			+15%
526 BOLLMANN		3 F	1,689	32,03	40	۷	/3,	342
			/					
							-	
			Bid Re	sults				
Addresses	Bidder 1	/	Bidder 2	Bidder 3		Bidder 4	4	Bidder 5
S	16MA		SCHULT	E ADRO	1	JASRO	re.	
526 BOWMAN 3	9,900	·	39,270	141,526	.63	41,95	0	
		<u> </u>	ON		1			
		/	V	A Fligh	<del></del>			
			Bid Walk A	ttendees				
ADROIT			SIGMA					MANAGE SAN STATE AND
SCHULTE			rasfin			,		
YUSHUA								
This is to certify that bids for th Office located at 600 E. Trade S Bids Opened By:	treet, Charlot	te, N	C.	opened and read a dids Recorded By:		, η		k Business Services
Note: Responsive bids are th		with	nin a range of 15%	above and 15% be	elow th	e public body	cost est	timate. As a



### SAFE HOME

**CITY OF CHARLOTTE** 

NEIGHBORHOOD & BUSINESS SERVICES

#### Company Acknowledgement:

The undersigned, having become thoroughly familiar with the terms, conditions, limitations, and provisions of the housing improvement work to be performed at <u>526 Bowman Rd.</u> to be funded through the City of Charlotte Neighborhood & Business Services, In addition, having fully inspected the site in all particulars, hereby proposes and agrees to fully perform the work within the time stated and in strict accordance with the proposed contract documents including furnishing of any and all labor and materials, and to do all work required to complete said Work in accordance with the advised respective contractual, for the sum of money:

the advised respective contractual, for the sum of money:

All labor, materials, services and equipment necessary for the completion of the Work shown on the Drawings and in the Specifications:

Written total

Specs Dated: 7/13/18

Number of Pages: 12 pages

Addenda # 1 Dated:

Number of Pages:

Number of Pages:

Project Schedule: Minimum Start Date - September 24, 2018

Completion Deadline: October 26, 2018

Please Print and Sign:	Ed	Sch	~~			
Company Name/Firm:	Scho	lte 1	Constr	·~		
Authorized Representa	tive Name: Æ	Ed Si	ch			
Signature:				Date:	8-8-18	

Prepared By: City of Charlotte Housing & Neighborhood Services 600 E, Trade Street Charlotte, NC 28202 (704) 336-7600

Property Details				
Address:	526 Bowman Rd.	Owner:	Joanne Smith	
	Charlotte, NC 28208	Owner Phone:	(980) 230-8816	
Structure Type:	Single Unit	Program(s):	Tested- HAS LEAD	
Square Feet:			LeadSafe 2016 SH FY18 Not Ranked	i .
Year Built:	1950		CITI TO NOT NAME	•
Property Value:				
Tax Parcel:	14513410			
Census Tract:				
Property Zone:		•		
Repairs				
·		•• • • • • • • • • • • • • • • • • • • •	Floor Room	<u>Exterior</u>
<u>Description</u>		•		,
Permits Required	slble obtaining and paying for all permits requ	ulrad Sald narmits s	hall include all Items in	this scope of work.
The contractor is respon	isiple obtaining and paying for all permite requ	anda, dala portino o	man morado di namo in	15000
	Bid	Cost:	=_	630,
		Base	Quantity	Total Cost
Portable Toilet				
Provide temporary tollet	facilities from job start until approval of perma	anent facilities.		<b>6</b> 2
			V	200,00
	Bid	Cost: Base	Quantity	Total Cost
		2400	Quartity	, σ,α, σσσ.
Trash Removal				
After procuring all required debris using dust control away dally using dump	ed permits, place AS MANY roll-off dumpster I methods, Remove dumpster and repair any trailers	rs as needed without evidence of the dum	t damaging the site. Co npsters use. Contractor	llect construction may haul debris
andy daily doing dailip	··		."	600.00
	Bld	Cost:	_X=_	
		Base	Quantity	Total Cost

Response Due: 7/13/2018 3:00 pm

l

# **Work Specification**

		l 4 .	e Teri	16
HVI	arm	INST	3 1 6 6	THITIAL

Exterminate refmites				•
Exterminate for termites. Drill and patch foundation and paven year guarantee with an optional yearly renewable warranty for	nent where nece the homeowne	essary, Extern r		
year guarantee with an optional yearly range series with any			v	1200.00
	Bld Cost:	Base	A	Total Cost
Crawl Space Access Door			Exterior	
Remove existing crawl entry door and dispose of properly.				
PAINTED MATERIALS ARE COATED WITH LEAD BASED P	AINT, USE LE	AD <sub>.</sub> SAFE WO	RK PRACTICES.	
Install a 3/4" pressure treated plywood access door in a 2" x 4	" pressure treat	ed frame. Pro	ovide galvanized iro	n hinges and hasp.
	Bid Cost:		<b>Υ</b> =	150,0
	Did Cost:	Base	Quantity	Total Cost
Electric Service 200 AMP		•	Building Sy	/stems
Replace electrical service with new 200 amp, main disconnec	t, 110/220 volt, :	24 circuit pane	el board, meter soci	ket, weather head,
service cable, ground rods and cable. Include replacement of	all sub-panels.	Caulk exterio	r service penetratio	n,
Install GFCI breakers on all existing receptacle circuit.				•
Install GFCI/AFCI combination breakers on all existing receptor	acie circults ser	vloing bedroor	ns.	
INCLUDES REPAIR OF VINYL SIDING AT SERVICE AS NE	CESSARY.			
	Bld Cost:		x =	2800
	Bid 003ti	Base	Quantity	Total Cost
Smoke Detectors Hard Wired			Building Sy	/stems
Install UL approved, interconnected, ceiling mounted smoke a battery backups in bedrooms and outside of sleeping areas.	and heat detecto	ors permanent	ly wired into a rece	ptacle boxes with
Detector in the hall way shall be a combination smoke and CO	o detector.			
	Bid Cost:		Y =	750
	Bid Cost:	Base	Quantity	Total Cost
Add Outlet Circuit			Electrical	
Add new outlet circuit with two outlets in each bedroom and the	nree outlets in th	ne living room	. Protect circuit with	n an AFCI breaker.
Scope includes repair of all damage to finished surfaces.				
			V	: 2000
	Bld Cost: _	Base	X= Quantity	Total Cost
		<b>2000</b>	Squartity	10141 0001

Replace Receptacles, Switches, and Plates

**Building Systems** 

Replace all receptacles, switches and cover plates throughout entire house EXCEPT IN CODE DEFINED DAMP LOCATIONS.

APPROXIMATELY 14 EXISTING RECEPTACLES, SIMILAR NUMBER OF SWITCHES,

All new receptacles shall be three prong. Note that the service panel line item specifies GFCI and AFCI protection on receptacle circuits so it is not necessary to pull a third wire. Receptacles must be labeled as required by Code.

Repair any damage to finish materials caused by this work.				- M
	Bld Cost:		х=_	900.00
		Base	Quantity	Total Cost
Dryer Circuit			LAUND	24
Remove existing dryer outlet and wiring.				
Install 220 volt, 30 amp, surface mounted receptacle on an indirequired.	vidual circuit at	designated	new location. Repair a	ll wall tear out
requiredi	Bld Cost:		X =	250,00
		Base	Quantity	Total Cost
GFCI Receptacle			Laundry	
Install a GFCI receptacle in the existing outlet box.	-	•		55.00
	Bid Cost:			
		Base	Quantity	Total Cost
GFCI Receptacle 20 AMP			KITCHE	
Install a flush mounted, ground fault circuit interrupted, duplex in	eceptacle and	cover plate	on a new circuit over th	
left of the sink. Fish wire and repair all tear out as needed.				250,20
	Bid Cost:	Base	_X = _=_ Quantity	Total Cost
		pase	·	rotal oost
GFCI Device Exterior			Exterior	
Install surfaced mounted ground fault circuit interrupt receptacl entry doors.	es in weather p	roof In use o		
·	Bld Cost:		Х =	750
		Base	Quantity	<b>Total Cost</b>
Light Fixture Exterior			FRONT	PORCH
Replace two front porch lights with UL approved, LED light fixtu	ures of similar o	iesign.		_
	Bid Cost:		х =	75
		Base	Quantity	Total Cost

Florescent Light Fixture with Cover

Kitchen

Remove existing ceiling fan and dispose of properly.

Install an Energy Star rated 4' florescent fixture with 4 tubes and a wrap around shade. Materials and installation shall conform to the Construction Standards and the Electrical Code.

Construction Standards and the Electrical Code.							
	Bld Cost:	>	(	= 100,00			
1		Base	Quantity	Total Cost			
Remove Tub and Surround and Install Shower with Grab I	3ars		Bathroom				
Remove existing tub and surround, including valve and drain a	and dispose of p	roperly.					
Insulate open exterior wall cavity with R-13.							
Install blocking for three grab bars at locations determined by	rehab specialist	and home ow	ner.				
Install a fiberglass shower pan with a built in seat. Pan must be	e pre-approved	by City rehab	specialist.				
Install coment tile backer board and a ceramic tile surround.							
Install new drain and mixing valve with all associated plumbing lines. Mixing valve shall be located in the center of the long wall of the shower to be accessible from a seated position. Install a diverter valve with a handheld sprayer beside the mixing valve. Shower head shall be located as normal. Install grab bars at designated locations.							
Install tempered glass sliding shower doors.							
All materials and work shall comply with the Construction Spe	cifications and t	he Plumbing C	Gode.	111000			
	Bld Cost:		Κ	= 4/000			
		Base	Quantity	. Total Cost			
Hose Blbb			Building :	Systems			
install frost free bronze hose blbbs on outside of structure wit with silicone caulk.	h inside shut-ofi	valve and bad	ckflow preventer.	Seal exterior penetration			
Replace approximately 20 linear feet of existing galvanized su	ipply line with P	EX to existing	CPVC.				
Replace existing hose blbb at front of house and add hose blb	b at rear of hou	se,					
TWO TOTAL			١,	- /			
	Bld Cost:		x	<u> 750</u>			
		Base	Quantity	Total Cost			

HOLK Obookings				
Double Bowl Sink Complete			Kitchen	
Install a 18 gauge 33" x 22" x 8" double bowl, stainless steel, so rated at 2.0 GPM or less, with a 15 year drip- free warranty, P- on all supply & drain lines. No copper compression fittings.	əlf rimming kitol trap, supply line	nen sink ind es, full port	luding a single han ball type shut-off va	alves & escutoneon plates
				<sub>2</sub> 800.00
	Bld Cost:		_X	
		Base	Quantity	* Total Cost
Remove Garbage Disposal			Kitchen	
Remove garbage disposal and replumb with standard drain line	e. Terminate w	lre in box.		
				100
	Bid Cost:		_X	= <u> </u>
		Base	Quantity	Total Cost
Dishwasher			Kitchen	
Install a 2-cycle dishwasher that is EnergyStar rated. Owner's	choice of color.			
•				_ 650
	Bid Cost:		_X	Total Cost
		Base	' Quantity	(Old) Gost
Move Air Return and Repair Floor			Hall	
Relocate air return to be wall mounted in a newly framed chase joist. Frame, finish, and trim a drywall box to enclose the air re to match existing as close as possible.	e in front of the sturn. Top shall	old chimne I have 1/2" ¡	y. Will require hea olywood under the	iding off one short floor drywall for strength. Paint
Repair or replace ductwork as necessary to connect to the retu	ırn in the new lo	ocation.		
Remove grate and other materials from the old floor furnace. I plank flooring in the hall with new finished quarter round moldli	Frame in openir ng and transitio	ng and cove n strips at d	er with subfloor. In: loorways.	stall interlocking vinyl
	Did Oanti		х	- 1,200
	Big Cost:	Base	Quantity	Total Cost
		<b>,</b>	•	
Move Supply Vent			DEN	
Move the supply vent under the window in the den to a new lo floor as necessary to match existing as close as possible.	cation on the sa	ame wall to	be out of the way o	of the new door. Repair
			v	_ (00
	Bld Cost: _	Base	X Quantity	Total Cost
		Dase	Quantity	Total Gost
Dryer Vent			Laundry	
Install 4" rigid aluminum vent tubing from the specified dryer ic and NO screening. Fasteners shall not protrude into the inter or aluminum foil tane, not duct tape. Secure duct and hood to	flor of the exhau	vall mounte ust duct. Se	d dryer vent hood v eal all seams in the	with a back flow preventer system with duct mastic

Bid Cost:

Base

Quantity

**Total Cost** 

#### Range Hood Exterior Vented

#### Kitchen

Install an exterior ducted enameled range hood with integral controls and light capable of 100 cfm at 70 sones. Attach hood to cabinet with screws. Include metal vent and roof or wall cap/damper assembly, using #14 copper Romex. Owner's choice of color.

INSTALLATION INCLUDES BOXING IN THE DUCTWORK BETWEEN THE CABINET AND THE CEILING TO PRODUCE A FINISHED APPEARANCE THAT BLENDS WITH THE SURROUNDING MATERIALS.

	Bid Cost:		_X	=	100
		Base	Quantit	,	Total Cost
Re-Work Front Steps and Sidewalk			Genera	ıl Requi	rements
Water currently pools around the sidewalk at the base of the	front porch step	s. To correct	this problem:		
*remove the front steps					
*remove the sidewalk back to the first control joint					
* install a 4" PVC pipe in front of the porch foundation to allow the house	w water to flow fi	om the right	side of the hous	e to the	left side and around
* pour a new section of sidewalk from the control joint to the positive drainage away from the porch.	porch foundatlor	n. Angle of th	e sidewalk shal	be suffi	clent to Insure
* bulld a new brick step on top of the sidewalk to provide two	equal risers from	n the sidewal	k to the porch v	alking s	urface.
*regrade around porch and sidewalk as necessary to insure	water flow to and	d around the l	eft side of the h	ouse.	
*seed and straw disturbed areas.					
	Bld Cost:		x	= (	2/00
		Base	Quantit		Total Cost
Masonry Patch & Repoint			Exteri	or	
Install bricks where missing. Cut out mortar at least 1/2". Re repoint in 1/2" lifts using portland cement mortar. Reinstall a	emove all loose r any flashings, too	naterial with o	clear water. Sati nts and clean bi	ırate join lck face.	its with water and
	Bid Cost:		x	= 4	/4()·
	Bid Gosti _	Base	Quantit	y ·	Total Cost
Seal Foundation	:		Exteri	or	·
Seal foundation where the sewer pipe penetrates the foundation	ation from the int	erlor using hy	draulic cement.		
Pump any standing water out of crawl.					
Add sufficient topsoil to the exterior of the foundation to insu the foundation. Seed and straw disturbed areas.	ire positive drain	age away froi	n the area whe	e the se	wer line penetrates
	Bid Cost:		x	=	120
		Base	Quantil	у	Total Cost

Vinyl Windows

Living Room

Dispose of window units and any security bars. Field measure, order and install new Energy Star rated vinyl, double glazed LOW- E windows including half screens. Insulate rough opening. Install new extension jambs, casing and sill as needed, prime and paint. Exterior trim to be wrapped in PVC coated aluminum coll as needed. Repair all areas disturbed by removal and installation. This installation is to include repairing any damaged header, framing (to include king studs, jack studs etc.) sub-floor, floor joists, band joists and sill.

THE EXISTING BAY WINDOW CONSTRUCTION IS TO BE COMPLETELY REMOVED AND THE SIDING REPAIRED AS NECESSARY, USE SIDING FROM THE REAR OF THE HOUSE TO INSURE AN EXACT MATCH IN COLOR.

New windows will be installed flat in the plane of the front wall. Large ploture window in center with small single hung windows on both sides.

Scope also includes replacing small vinyl window to the left of the fireplace.

NO GRIDS IN WINDOWS			1	1.000
	Bid Cost;	x_		1800
		Base	Quantity	Total Cost
Vinyl Window			Bedroom fro	ont
Dispose of window units and any security bars. Field measure, windows including half screens. Insulate rough opening. Install Exterior trim to be wrapped in PVC coated aluminum coil as ne installation is to include repairing any damaged header, framing joists and sill.	new extension j eded. Repair all g (to include king	ambs, casing a areas disturbe	nd sill as needed, i by removal and	prime and paint. Installation. This
NO GRIDS IN WINDOWS				L 0 0 1 1 00
	Bld Cost:	x_	=	10000,50
•		Base	Quantity	Total Cost
Vinyl Window			Bedroom	
Dispose of window units and any security bars. Field measure, windows including half screens. Insulate rough opening. Install Exterior trim to be wrapped in PVC coated aluminum coil as ne installation is to include repairing any damaged header, framin joists and sill.	new extension j eded, Repair all	ambs, casing a areas disturbe	nd sill as needed d by removal and	, prime and paint. Installation, This
REPLACE OLDER VINYL WINDOW ONLY.				
NO GRIDS IN WINDOWS	Bld Cost:	¥	=	450
	Blu Cost:	Base	Quantity	Total Cost

Repair Window			Kitchen				
Repair window over kitchen sink to open and close smoothly ar	nd to lock prop	erly.		_			
	Bld Cost:	x		_ 25			
	Bid Cost	Base	Quantity	Total Cost			
Repair Window			Bathroon	1			
Repair window to open and close smoothly and to lock properly	<i>/</i> ,						
				75			
	Bld Cost:	X_		= <u> </u>			
		Base	Quantity	Total Cost			
Re-Configure Laundry Room			Laundry				
The present laundry room was a poorly done and incomplete renovation of the back porch begun by the previous owner. It will not readily accommodate both a washer and a dryer. To make the laundry room truly functional, we will be removing the existing exterior door to the deck and closing the opening. The following items are required to complete the re-working of the laundry room:							
*Remove existing exterior door and storm door at the laundry re	oom. Save sto	rm door for re-ir	nstallation.				
*Frame in door opening, install 7/16" OSB on the exterior, insulation with the surrounding wall surfaces.	ate the open v	/all area with R-′ ·	13, and hang a	nd finish 1/2" drywall to			
*Install baseboard							
*Replace vinyl siding on exterior of wall to match existing siding	g as close as p	ossible.					
*Remove existing floor covering to the transition strip at the refinecessary to provide smooth flooring transitions to the kitchen	rigerator. Rem and the den.	ove underlayme	ont to the subfic	oor, Level subfloor as			
*Install interlocking vinyl plank flooring. Owner choice of patte	rn and color.						
	Bid Cost;	х		- 2200			
		Base	Quantity	Total Cost			

Remove Window/install Door
Remove window in den.

DEN

Reframe opening to accommodate a 3-0 x 6-8 door. Install sheathing on exterior as needed and insulate open wall cavities.

Hang and finish drywall on interior side as necessary to blend with surrounding wall surfaces.

Install a 3-0 x 6-8 full light metal door with leverset handle and deadbolt keyed alike. Paint door to match existing,

Repair baseboard as necessary.

Paint wall and associated trim from corner to corner to match the existing as close as possible.

Repair vinyl siding on the exterior to blend with the existing as close as possible.

Re-install storm door.

	Bld Cost:	٠,	<b>(</b>	= 2100
		Base	Quantity	Total Cost
Floor System Repair		C	عمد	SPACE
Sister four mold damaged floor joists full length with pressure to	eated 2 x 12s	n the area und	derneath the li	ving room at the front entry.
	Bid Cost:		ζ	<u> , 1800</u>
		Base	Quantity	Total Cost
Patch, Finish, Prep & Paint Room Semi Gloss			Kitchei	1 .
Remove or cover hardware, furnishings, and accessories not to oil, grease, fungus, dirt, and dust from surfaces.	be painted. S	crape loose, p	eeling, cracke	d and blistered areas, Clean
Remove vents above washing machine and patch wall. Fill hold celling surfaces and sand to a feather edge.	es and cracks.	Repair all roug	h, damaged, d	or unfinished wall and
Prime all new materials and spot prime existing with acrylic later. Painting shall include ceilings, walls, all trim, and doors.	x. Top coat wl	h owner's cho	lce of low VO	C acrylic SEMI-GLOSS
Replace or uncover hardware, fixtures and accessories. Any m	oving of furnitu	re required sh	all be included	800
	Bld Cost:		<	_=
		Rase	Quantity	Total Cost

### Patch Plaster, Prep& Paint Room

#### **Bedroom front**

Remove or cover hardware and accessories not to be painted. Scrape loose, peeling, cracked, and bilstered areas. Clean oil, grease, fungus, dirt, and dust from surfaces. Fill holes and cracks.

Repair rough areas to produce a smooth paintable surface.

Prime all new materials and spot prime existing with acrylic latex. Top coat with Owner's choice of low VOC acrylic flat latex.

. Replace or uncover hardware, fixtures and accessories. Covering and moving furniture as required shall be included.

PAINTING SCOPE INCLUDES WALLS, CEILINGS, ALL TRIM AND DOORS. CLOSET INTERIORS ARE EXCLUDED.

	Bid Cost:		X	<u>. 800                                   </u>			
	·.	Base	Quantity	Total Cost			
Patch Plaster, Prep & Paint Room		Bedroom					
Remove or cover hardware and accessories not to be painted fungus, dirt, and dust from surfaces, Fill holes and cracks.	d. Scrape loose,	peeling, craci	red, and blistered a	areas. Clean oll, grease,			
Repair rough areas to produce a smooth paintable surface. Prime all new materials and spot prime existing with acrylic is	atex. Top coat wil	h Owner's ch	olce of low VOC a	crylic flat latex.			
Replace or uncover hardware, fixtures and accessories, Cover	ering and moving	furniture as i	required shall be in	oluded,			
PAINTING SCOPE INCLUDES WALLS, CEILINGS, ALL TRIM AND DOORS. GLOSET INTERIORS ARE EXCLUDED.							
	Bld Cost:		X	* 800			
		Base	Quantity	Total Cost			
Prep & Paint Room Semi Gloss		Bathroom					
Remove or cover hardware and accessories not to be painte	d.						
Scrape loose, peeling, cracked and blistered areas. Clean of sand to produce a smooth paintable surface. Prime all new nuchoice of low VOC acrylic SEMI-GLOSS latex.	l, grease, fungus naterlals and spo	, dirt, and dus t prime existli	it from surfaces. Fi ng with acrylic late:	ll holes and cracks and k, Top coat with owner's			
Replace or uncover hardware, fixtures and accessories. Any	moving of furnitu	ıre required s	hall be included.				
PAINTING SCOPE INCLUDES WALLS, CEILING, ALL TRIM	M, AND DOORS.			- /			
	Bld Cost:		x	= 800			

Base

Quantity

**Total Cost** 

### Interlocking Vinyl Plank Flooring

BATHROOM

Install 25 year warrantled interlocking vinyl plank floor covering per manufacturer's specifications, include transitions and painted or stained wood quarter-round at all perimeters to complete installation.

INCLUDES RE-INSTALLATION OF COMMODE WITH NEW W	/AX SEAL,			
	Bld Cost:		х	<u>450</u>
	DIG 0030	Base	Quantity	Total Cost
Interlocking Vinyl Plank Flooring			LIVING	ROOM
Install 25 year warrantled interlocking vinyl plank floor covering stained wood quarter-round at all perimeters to complete install		rer's specifica	atlons, Include trat	nsitions and painted or
	Bld Cost:		X Quantity	<u> 1400</u>
,		Base	Quantity	Total Cost
Cabinet Repair			Kitchen	
Repair base cabinet under kitchen sink by installing plywood bo	ottom. Finish w	ith white sen	nl-gloss low-VOC p	oaint,
	Bld Cost:	•	x	<u>50</u>
	<u> </u>	Base	Quantity	Total Cost
Counter Tops Replace			Kitchen	
Screw to base cabinet a square edged plastic laminate counter adjoining walls with low VOC caulking to match wall color. Own	top. Provide e ner's choice of	nd-caps and In-stock color	cutout for sink. C	aulk counter top to
	Eld Costs		X	<u>400</u>
•	Bid 008(;	Base	Quantity	= 400 Total Cost
Replace Range			Kitchen	
Remove existing range and dispose of properly.				
Install a new four burner 30" electric range. Owner's choice of	color.			
INSTALLATION INCLUDES CHANGING PLUG AS NECESSA	RY TO ACCOM	MODATE N	IEW RANGE COR	kD,
	Bid Cost:		X Quantity	= 600
	<del></del>	Base	Quantity	Total Cost
Adjust Door			Bedroom	
Adjust door to latch and look properly without scrubbing on fram	ne.			, ,
	Bld Cost:		х	<u></u> 26
		Base	Quantity	Total Cost
• • • • • • • • • • • • • • • • • • • •				

Vinyl Siding - Repair		Exterior				
Replace three damaged vinyl corner posts.						
	Bld Cost:		х		=	800
		Base		Quantity		Total Cost
Power Wash Siding				Exterior		•
Vinyl Siding & trim. Remove stains and dirt from siding using damage to siding materials.	hlgh pressure w	ater and de	lergen	t mix. Adjust	pres	ssure to avold
	Bld Cost:		Х		=	OO
		Base		Quantity		Total Cost
Seamless Aluminum Gutter & Downspouts - Install				Bullding	Sys	tems
Install K- type .027 gauge seamless aluminum gutter to service by owner.	ce roof with suffi	clent pitch to	o dowi	nspouts. Wh	ite o	r brown color choice
Install at least 5 linear feet of drain line to each downspout to	direct water awa	ay from foun	datlor	١.		
FRONT ONLYI						
	Bid Cost:		х		=	750
		Base		Quantity		Total Cost
Exterior Handralls				Porch		
Remove existing handralls. Dispose of properly, Re-install ha to code.	ndralls to currer	nt building co	ode us	ing treated it	ımbe	er, Size & dimensions
	militar (		v		_	400
	Bld Cost:	Base	_^_	Quantity		Total Cost
Foundation Vent Screen				Exterior		
Replace 3 old foundation vents with solar powered vents.						
	Bld Cost:		х		=	200
	Dia 00011	Base		Quantity		Total Cost
Certification	٠					
Contractor Name: 5 cht Censtr	~			Total Co	st:	39270
Signature:	o *					8-18
				بـ		